

MAY 20 1999

MARI 53996

STATE OF OREGON WATER SUPPLY WELL REPORT (as required by ORS 537.765)

WATER RESOURCES DEPT. SALEM, OREGON

WELL I.D. # L None START CARD # 118502

Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number 1 Name Colin Macdonald Address 425 NW Royal Blvd City Portland State OR Zip 97210

(2) TYPE OF WORK [X] New Well [] Deepening [] Alteration (repair/recondition) [X] Abandonment

(3) DRILL METHOD: [X] Rotary Air [] Rotary Mud [] Cable [] Auger [] Other

(4) PROPOSED USE: [X] Domestic [] Community [] Industrial [] Irrigation [] Thermal [] Injection [] Livestock [] Other

(5) BORE HOLE CONSTRUCTION: Special Construction approval [] Yes [X] No Depth of Completed Well 0 ft. Explosives used [] Yes [X] No Type Amount

Table with columns: HOLE Diameter, From, To, Material, SEAL From, To, Sacks or pounds. Row 1: 6, 0, 223, Cement, 0, 223, 36 Sacks

How was seal placed: Method [] A [] B [X] C [] D [] E Backfill placed from ft. to ft. Material Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Casing: None

(7) PERFORATIONS/SCREENS: Table with columns: From, To, Slot size, Number, Diameter, Tele/pipe size, Casing, Liner

(8) WELL TESTS: Minimum testing time is 1 hour [] Pump [] Bailer [] Air [] Flowing Artesian Yield gal/min 5 Drawdown 220 Drill stem at 1 hr

Temperature of water 56 Depth Artesian Flow Found Was a water analysis done? [] Yes By whom Did any strata contain water not suitable for intended use? [] Too little [] Salty [] Muddy [] Odor [] Colored [] Other Depth of strata:

(9) LOCATION OF WELL by legal description: County Marion Latitude Longitude Township 8-S N or S Range 3-W E or W. WM. Section 33 SE 1/4 NW 1/4 Tax Lot 100 Lot Block Subdivision Street Address of Well (or nearest address) 8371 Liberty Road S Salem OR

(10) STATIC WATER LEVEL: 32 ft. below land surface. Date 5-5-99 Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES: Depth at which water was first found 58

Table with columns: From, To, Estimated Flow Rate, SWL. Row 1: 58, 59, 2-3, 32. Row 2: 130, 191, 2-3, 56

(12) WELL LOG: Ground Elevation

Table with columns: Material, From, To, SWL. Rows: Red top soil (0-2), Red Clay (2-24), Bronish Red Clay (24-48), Decomposed basalt (48-101), Weathered gray basalt (101-120), Gray basalt (120-124), Black basalt (124-130), Weathered basalt (130-134), Weathered black basalt with tan clay (134-144), Gray basalt (144-145), Fractured gray basalt (145-156), Fractured black basalt (156-191), Multi-colored Clay (191-211), Gray Clay (211-223). Well was abandoned due to lack of water.

Date started 5-4-99 Completed 5-5-99

(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

Signed [Signature] WWC Number 1703 Date 5-9-99

(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

Signed [Signature] WWC Number 1273 Date 5-9-99