

RECEIVED

SEP 08 1999

POLK 51007

STATE OF OREGON WATER SUPPLY WELL CONSTRUCTION DEPT. SALEM, OREGON

WELL I.D. # 33115 START CARD # 122347

Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number Name Mark + Pam Geiger Address 1463 35th Ave NW City Salem State OR Zip 97304

(2) TYPE OF WORK [X] New Well [] Deepening [] Alteration (repair/recondition) [] Abandonment

(3) DRILL METHOD: [X] Rotary Air [] Rotary Mud [] Cable [] Auger [] Other

(4) PROPOSED USE: [X] Domestic [] Community [] Industrial [] Irrigation [] Thermal [] Injection [] Livestock [] Other

(5) BORE HOLE CONSTRUCTION: Special Construction approval [] Yes [X] No Depth of Completed Well 390. Explosives used [] Yes [X] No Type Amount

Table with columns: HOLE Diameter, SEAL From, To, Material, From, To, Sacks or pounds. Includes entries for 10" diameter cement seal and 6" diameter bentonite seal.

How was seal placed: Method [] A [] B [X] C [] D [] E Backfill placed from ft. to ft. Material Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Includes entries for 6-inch casing and 4-inch liner.

Final location of shoe(s) None Used

(7) PERFORATIONS/SCREENS: Table with columns: From, To, Slot size, Number, Diameter, Material, Casing, Liner. Includes entry for 3/8 inch slot size.

(8) WELL TESTS: Minimum testing time is 1 hour. [] Pump [] Bailer [X] Air [] Flowing Artesian. Yield gal/min 30+, Drawdown, Drill stem at 390, Time 1 hr.

Temperature of water 53 Depth Artesian Flow Found Was a water analysis done? [] Yes By whom Did any strata contain water not suitable for intended use? [] Too little [] Salty [] Muddy [] Odor [] Colored [] Other Depth of strata:

(9) LOCATION OF WELL by legal description: County Polk Latitude Longitude Township 7-S N or S Range 3-W E or W. WM. Section 17 NW 1/4 NW 1/4 Tax Lot 4900 Lot Block Subdivision Street Address of Well (or nearest address) 7367 Grice Hill Ct

(10) STATIC WATER LEVEL: 299' 6" ft. below land surface. Date 8-3-99 Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES: Depth at which water was first found 124

Table with columns: From, To, Estimated Flow Rate, SWL. Includes entries for 124-128 ft depth with flow rate 1/2 and 313-390 ft depth with flow rate 30+ and SWL 299' 6".

(12) WELL LOG: Ground Elevation

Table with columns: Material, From, To, SWL. Lists geological layers such as Top Soil, Hbrd red clay, Soft red clay w/silt, Decomposed basalt, Tan clay, Gray clay, Weathered basalt, Black basalt, Gray basalt, Soft gray basalt, Gray basalt, Hard gray basalt, Fractured black seams, Simi weathered basalt, Weathered basalt, Porous basalt casing.

Date started 7/22/99 Completed 8/21/99 (unbonded) Water Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WWC Number 1629 Signed Date 8-3-99

(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief. Signed Date WWC Number