

RECEIVED

SEP - 9 1997

Wash 52537

Page 1

STATE OF OREGON WATER SUPPLY WELL CONSTRUCTION PERMITS WATER RESOURCES DEPT. SALEM, OREGON

WELL I.D.# L18227

(START CARD) # 103183

Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number Name DAVIS MANAGEMENT CO. Address 3285 NW SAUSBAUER RD. City CORNELIUS State OR. Zip 97113

(2) TYPE OF WORK [X] New Well [] Deepening [] Alteration (repair/recondition) [] Abandonment

(3) DRILL METHOD: [X] Rotary Air [X] Rotary Mud [] Cable [] Auger [] Other

(4) PROPOSED USE: [] Domestic [] Community [] Industrial [X] Irrigation [] Thermal [] Injection [] Livestock [] Other

(5) BORE HOLE CONSTRUCTION: Special Construction approval [] Yes [X] No Depth of Completed Well 510 ft. Explosives used [] Yes [X] No Type Amount

Table with columns: HOLE Diameter, SEAL From, To, Material, From, To, Sacks or pounds. Rows include Cement/Gel and Drill gel.

How was seal placed: Method [] A [] B [X] C [X] D [] E [] Other

Backfill placed from ft. to ft. Material Gravel placed from ft. to ft. Size of gravel

(6) CASING/LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Rows for Casing and Liner.

Final location of shoe(s)

(7) PERFORATIONS/SCREENS: Table with columns: From, To, Slot size, Number, Diameter, Material, Casing, Liner.

(8) WELL TESTS: Minimum testing time is 1 hour. Table with columns: Pump/Bailer/Air/Flowing Artesian, Yield, Drawdown, Drill stem at, Time.

Temperature of water 66 F Depth Artesian Flow Found Was a water analysis done? Did any strata contain water not suitable for intended use? Depth of strata:

(9) LOCATION OF WELL by legal description: County WASHINGTON Township 1N N or S Range 3W E or W. WM. Section 27 NW 1/4 NW 1/4 Tax Lot 500 Lot Block Subdivision Street Address of Well (or nearest address) 3285 NW SAUSBAUER RD.

(10) STATIC WATER LEVEL: 36 ft. below land surface. Date 09/05/97 Artesian pressure lb. per square inch. Date

(11) WATER BEARING ZONES: Depth at which water was first found 1380

Table with columns: From, To, Estimated Flow Rate, SWL. Row: 1380, 1510, 350 GPM, 36

(12) WELL LOG: Ground Elevation

Table with columns: Material, From, To, SWL. Rows include Brown Clay, Gray silty clay, Sticky gray clay, etc.

Date started 07/17/97 Completed 09/05/97

(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards.

(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above.

SEP - 9 1997

Wash 52537

Page 2

STATE OF OREGON WATER RESOURCES DEPT. WATER SUPPLY WELL REPORT SALEM, OREGON (as required by ORS 537.765)

WELL I.D.# 18227

(START CARD) # 103183

Instructions for completing this report are on the last page of this form.

(1) OWNER: Well Number _____ Name DAVIS MANAGEMENT CO. Address 3285 NW SAUSBAUER RD. City CORNELIUS State OR Zip 97113

(2) TYPE OF WORK [X] New Well [] Deepening [] Alteration (repair/recondition) [] Abandonment

(3) DRILL METHOD: [X] Rotary Air [X] Rotary Mud [] Cable [] Auger [] Other

(4) PROPOSED USE: [] Domestic [] Community [] Industrial [X] Irrigation [] Thermal [] Injection [] Livestock [] Other

(5) BORE HOLE CONSTRUCTION: Special Construction approval [] Yes [X] No Depth of Completed Well 510 ft. Explosives used [] Yes [X] No Type _____ Amount _____

Table with columns: HOLE Diameter, SEAL From, SEAL To, Material, Sacks or pounds. Includes rows for Cent/Gel and Cement seals.

(6) CASING/LINER: Table with columns: Diameter, From, To, Gauge, Steel, Plastic, Welded, Threaded. Includes rows for Casing and Liner.

Final location of shoe(s) _____

(7) PERFORATIONS/SCREENS: Table with columns: From, To, Slot size, Number, Diameter, Material, Casing, Liner.

(8) WELL TESTS: Minimum testing time is 1 hour. Table with columns: Yield gal/min, Drawdown, Drill stem at, Time. Includes rows for Pump, Bailer, Air, and Artesian tests.

Temperature of water 66° F Depth Artesian Flow Found _____ Was a water analysis done? [] Yes By whom _____ Did any strata contain water not suitable for intended use? [] Too little [] Salty [] Muddy [] Odor [] Colored [] Other _____ Depth of strata: _____

(9) LOCATION OF WELL by legal description: County WASH. Latitude _____ Longitude _____ Township 1N N or S Range 3W E or W. WM. Section 27 NW 1/4 NW 1/4 Tax Lot 500 Lot _____ Block _____ Subdivision _____ Street Address of Well (or nearest address) 3285 NW SAUSBAUER RD.

(10) STATIC WATER LEVEL: 36 ft. below land surface. Date 09/05/97 Artesian pressure _____ lb. per square inch. Date _____

(11) WATER BEARING ZONES: Depth at which water was first found 1380

Table with columns: From, To, Estimated Flow Rate, SWL. Includes row for 1380 to 1510 ft. with 350 gpm flow rate and 36 ft. SWL.

(12) WELL LOG: Ground Elevation _____

Table with columns: Material, From, To, SWL. Includes rows for Hard gray basalt and Soft brown basalt.

Date started 07/17/97 Completed 09/05/97

(unbonded) Water Well Constructor Certification: I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon water supply well construction standards. Materials used and information reported above are true to the best of my knowledge and belief.

WVC Number _____ Signed _____ Date _____

(bonded) Water Well Constructor Certification: I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon water supply well construction standards. This report is true to the best of my knowledge and belief.

WVC Number 1266 Signed _____ Date 09/05/97