

MONITORING WELL REPORT

(as required by ORS 537.765 & OAR 690-240-095)

Instructions for completing this report are on the last page of this form.

Well ID# 438470

Start Card # 130047

JUL 28 2000

(1) OWNER/PROJECT: WELL NO. DMW-15A

Name Spiker Properties, LP
Address 4949 SW Meadows Rd Ste 260
City Lake Oswego State OR Zip 97035

(2) TYPE OF WORK:

- New construction [X]
Alteration (Repair/Recondition) []
Conversion []
Deepening []
Abandonment []

(3) DRILLING METHOD

- Rotary Air [X]
Rotary Mud []
Cable []
Hollow Stem Auger []
Other []

(6) LOCATION OF WELL By legal description

Well Location: County Washington
Township 15 (N or S) Range 1W (E or W) Section 27


1. NW 1/4 of SE 1/4 of above section.
2. Either Street address of well location
9560 SW Nimbus Dr. Beaverton, OR
or Tax lot number of well location 500

3. ATTACH MAP WITH LOCATION IDENTIFIED. Map shall include approximate scale and north arrow.

(7) STATIC WATER LEVEL:

11' Ft. below land surface. Date 5/22/00
Artesian Pressure lb/sq. in. Date

(4) BORE HOLE CONSTRUCTION



(8) WATER BEARING ZONES:

Table with columns: From, To, Est. Flow Rate, SWL. Data rows show water levels at 0, 30, 70, and 97 feet depths.

(9) WELL LOG:

Table with columns: Material, From, To, SWL. Lists geological layers like sand, basalt, and grout with their respective depths.

(5) WELL TEST:

Pump [] Bailer [] Air [] Flowing Artesian []
Permeability Yield GPM
Conductivity PH
Temperature of water 56 F/C Depth artesian flow found ft.
Was water analysis done? [] Yes [] No
By whom?
Depth of strata to be analyzed. From ft. to ft.
Remarks:

Name of supervising Geologist/Engineer
OR 0112 ORIGINAL & FIRST COPY-WATER RESOURCES DEPARTMENT

(unbonded) Monitor Well Constructor Certification:

I certify that the work I performed on the construction, alteration, or abandonment of this well is in compliance with Oregon well construction standards. Materials used and information reported above are true to the best knowledge and belief.

Signed [Signature] MWC Number 10464 Date 5-24-00

(bonded) Monitor Well Constructor Certification:

I accept responsibility for the construction, alteration, or abandonment work performed on this well during the construction dates reported above. All work performed during this time is in compliance with Oregon well construction standards. This report is true to the best of my knowledge and belief.

Signed [Signature] MWC Number 10024 Date 6/6/00
SECOND COPY-CONSTRUCTOR THIRD COPY-CUSTOMER

RECEIVED


WATER RESOURCES DEPT SALEM, OREGON

RECEIVED

JUN 08 2000

WATER RESOURCES DEPT SALEM, OREGON

- Legend**
- ⊕ DMW-1A Existing Basalt Monitoring Well
 - EW-1A Basalt Extraction Well
 - ⊕ DMW-15A Proposed Basalt Monitoring Well
 - Groundwater Sampling Location



Scale in Feet



Existing and Proposed CRBG Monitoring and Extraction Wells

Figure 2-3

RECEIVED

JUN 08 2000

RECEIVED

JUL 28 2000

WATER RESOURCES DEPT.
SALEM, OREGON

WATER RESOURCES DEPT.
SALEM, OREGON

